



# Installation

## VK/02270

SINCE 1978



LEADING LIGHT

Please read the instructions carefully before commencing assembly

**Step 1:** Unboxing and identification of parts. Part A is the main housing. Parts B, C, D, and E are screws and washers. Tools include a PZ screwdriver, a Phillips screwdriver, a pencil, a spirit level, and a power drill. A 30-minute timer and a person icon indicate the estimated installation time.

**Step 2:** Mounting the base plate (A) to the wall. Dimensions 35mm and 70mm are shown. A 5mm hole is marked for the base plate. A warning symbol indicates electrical safety.

**Step 3:** Drilling a 5mm hole in the wall. A 5mm drill bit is used. A warning symbol indicates electrical safety.

**Step 4:** Inserting the base plate into the wall hole. A PZ screwdriver is used to secure the base plate. A warning symbol indicates electrical safety.

**Step 5:** Mounting the light fixture to the base plate. A PZ screwdriver is used to secure the fixture. A warning symbol indicates electrical safety.

**Step 6:** Final assembly and adjustment. The light fixture is adjusted to the desired position. A warning symbol indicates electrical safety.

**Step 7:** Final check and completion. The light fixture is shown fully installed. A warning symbol indicates electrical safety.

VK Leading Light / Vaios I. Karakostas S.A. Imports - Exports Trade

A: 8 Aristotelous St, Tavros, 177 78 Athens, Greece T: +30 210 99 69 610-11, +30 210 34 58 072, +30 210 34 58 075  
 F: +30 210 99 58 374 E: info@vkleadinglight.gr W: vkleadinglight.gr